

Graham Hurford Quality Homes P/L T/A InSpec Building & Pest Inspections License No 36640C 4 Stewart close ORANGE NSW 2800 Tel: 0418 635 783 info@inspecbuildingandpest.com.au

Pre-Purchase Inspection - Residential Building Report

Complies with Australian Standard AS 4349.1- 2007 Inspection of Buildings Part 1: Pre-Purchase inspections - Residential buildings



1185 Packham Dr Molong

PURPOSE OF INSPECTION

The purpose of the inspection is to identify the major defects and safety hazards associated with the property at the time of the inspection. The inspection and reporting is limited to AS4349.1-2007 and the Building Inspection Agreement.

The overall condition of this building has been compared to similarly constructed & reasonably maintained buildings of approximately the same age.

If it is more than 60 days from the inspection date, we recommend a new inspection and report. If the property is being auctioned refer to the Disclaimer of Liability to Third Parties in this report.

Property Inspected

Property Inspected Details:

Re: 1185 Packham Dr Molong NSW 2866

| Inspection Requested By: | Cathy & Tony Mileto cathymileto7@gmail.com Re: 1185 Packham Dr Molong NSW 2866 |
|---|---|
| Inspection Requested For: | Same as Inspection Requested By |
| Cost Billed To: | Same as Inspection Requested By |
| Contact For Access: | Jodie Murray McGrath Molong 10 Bank St Molong NSW 2866 |
| Inspection Details | |
| Work Order/Reference Number: | 0081 |
| Inspection Date/Time: | 05/09/2022 3:00 PM |
| Persons in attendance: | None |
| Other relevant comments: | Nil |
| Weather conditions at time of inspection: | Sunny |
| Agreement Details | |
| Agreement Number: | 0081 |
| Date of Agreement: | 05/09/2022 3:00 PM |
| Specific requirements and or conditions required: | Nil building report only |

Should you have any difficulty in understanding anything contained within this report then you should immediately contact the inspector and have the matter explained to you prior to acting on this report.

| Inspector Details | |
|--------------------------|--|
| Name Of Inspection Firm: | Graham Hurford Quality Homes P/L T/A InSpec Building & Pest Inspections License No 36640C |
| Contact Phone: | 0418 635 783 |
| Inspector Name: | Graham Hurford |
| Report Prepared Date: | 06/09/2022 |

Major Structural Defects identified to the Residential Building on day of inspection

There are no Major Structural Defects.

| Major Structural Defects identified beyond the Residential Building | No |
|---|---|
| Incidence of Major Defects | ТурісаІ |
| Incidence of Minor Defects | ТурісаІ |
| Overall Condition (refer to definitions) | Average |
| Details of possible concealment of defects: | The inspection is a reasonable attempt to identify major defects and safety hazards at the time of inspection. Whilst a thorough visual inspection of the property was carried out the element of concealment of defects is always possible. The inspector cannot and will not move any furniture, floor coverings eg: floor rugs, personal items. The inspector cannot see through walls, floors, paint etc The report is not a warranty against problems arising in the future. Defects reported can further deteriorate or become a safety hazard if not attended to by a qualified professional. This is not a Structural Engineers Report. Where defects of a structural nature are identified, a Structural Engineers report maybe required |

STRUCTURES INSPECTED For the purpose of reporting on the property the property will be defined by compass readings e.g. North face.

1.1 1185 Packham Dr Molong

| Structure type: | Freestanding house |
|--------------------------------|---|
| Orientation: | North |
| Areas Inspected: | Bathroom 1, Bedroom 1, Bedroom 2, Bedroom 3, Bedroom 4, Decking, Dining Room, Family Room, Roof Exterior, Hallway, Kitchen, Laundry, Lounge Room, Roof Void, Subfloor, Verandah, Walls Exterior |
| Is the building furnished?: | No |
| Construction type: | Timber frame-cladding |
| Pier type: | Masonry, Timber |
| Flooring type: | Compressed Sheet, Concrete Slab, Tongue and Groove Particle Board |
| Verandah: | Location: North |
| Decks: | Location: North |
| Roof Structure/s: | Pitched timber, Trussed timber, Skillion, Cathedral Ceiling |
| Roof covering/s: | Metal |
| Pool present: | No |
| Are Smoke Detectors Installed: | Yes Number of smoke detectors: 1 Location of smoke detectors: Hallway Recommendation: All smoke detectors should be tested for serviceability and compliance. |

General Comments:

Nil

AREAS WITHOUT ISSUE ON THE DAY OF INSPECTION

In relation to the Inspection Agreement, the overall condition of the following areas are consistent with buildings of approximately the same age and construction. Bedroom 1 Bedroom 2 Dining Room Kitchen Access Issue Type:

Restricted Access

The inspector has made a reasonable visual assessment of that area within the limitations identified.

Pitch

Areas of the roof void could not be inspected due to height restrictions.

Reason(s) Why:

Defect 1. - Exterior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:



The cracking cladding on the external corner.



Vertical cracking on the sheet join.

North Side, West Side, South Side, East Side

Walls - Timber Frame

Damage

The cladding on the exterior of the property is cracking on the joins.

Further deterioration.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Renderer.



Vertical cracking on the sheet join



Vertical cracking on the sheet join.

Defect 2. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Bedroom 4

Ceiling Nails Popping

Damage

The nails are popping in the ceiling sheets.

Further deterioration and popping.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plasterer, Painter



There are popping nails that need to be repaired.

Defect 3. - Roof Exterior

| Defect Location: | Various Areas |
|------------------------|--|
| Defect Summary: | Eaves Fascia and Barges |
| Type of Defect: | Damage, Water penetration, dampness, Material deterioration |
| Description: | Barge boards has decayed The eave sheeting has dislodged from the fascia and the paintwork has deteriorated. |
| Ongoing Consequence: | Damage to surrounding elements |
| Opinion of Cracking: | Not Applicable |
| Building Professional: | Note: This defect should be referred to a qualified building professional for the repairs/scope of work required. |
| | Building Professional Required: Carpenter, Painter |



The damaged barge board.



The barge board has deteriorated



The fibro eave lining has dislodged from the fascia.



The damaged barge board.



The barge board has deteriorated and there is no barge roof capping installed.



The eave lining is damaged and the timber support beam paintwork has deteriorated.

Defect 4. - Exterior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

North Side

Decks

Installation

The stairs on the front deck do not comply.

Personal injury, Tripping hazard

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Carpenter



The steps do not comply to the current Australian Standards.

Defect 5. - Exterior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

South Side

The rear deck and steps

Damage, Installation

The rear steps do not comply and the deck has deteriorated and needs maintenance.

Further deterioration and a safety issue.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Carpenter



The rear deck needs maintenance.



The steps do not comply to current Australian Standards and are a safety issue.

Defect 6. - Exterior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Various Areas

The timber trimming and the timber railing around the subfloor area.

Damage, Water penetration, dampness, Material deterioration

The timber has deteriorated.

Further deterioration of the timber.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Carpenter, Painter



The damaged timber railing.



Water damaged timber trimming above the railing.



Water damaged timber trimming above the railing.

Defect 7. - Roof Exterior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

North Side

Roof Coverings

Material deterioration

Metal roofing has rusted

Water ingress to Roof Void

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Roof Plumber



The roof sheeting on the front verandah is showing rust deterioration.

Defect 8. - Interior

Defect Location: Bedroom 4 Metal Windows and Doors - Sash/Door Defect Summary: Operation Type of Defect: Operational Description: The rollers are damaged Ongoing Consequence: damage to the sash/door Opinion of Cracking: Not Applicable **Building Professional:** Note: This defect should be referred to a qualified building professional for the

qualified building professional for the repairs/scope of work required.

Building Professional Required: Glazier



The window running wheels have deteriorated and need replacing/adjusting.

Defect 9. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

- Ongoing Consequence:
- Opinion of Cracking:

Building Professional:

Various areas of the property.

Metal Windows and Doors - Glazing Seals

Material deterioration

The glazing seals have perished

Water ingress

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Glazier



The glazing seals in various areas of the property need replacing as they are perished.

Defect 10. - Interior

| Defect Location: | Bedroom 3 |
|------------------------|---|
| Defect Summary: | Metal Windows and Doors - Sash/Door Operation |
| Type of Defect: | Material deterioration |
| Description: | The rollers are damaged |
| Ongoing Consequence: | damage to the sash/door |
| Opinion of Cracking: | Not Applicable |
| Building Professional: | Note: This defect should be referred to a qualified building professional for the repairs/scope of work required. |
| | Building Professional Required: Glazier |



The running wheels need replacing/adjusting.

Defect 11. - Interior

Defect Location: Defect Summary: Type of Defect: Description: Ongoing Consequence: Opinion of Cracking: Building Professional: Bedroom 2

Timber Doors - Operation

Operational

The door is binding.

Difficult to operate, Damage to surrounding elements

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Carpenter



The door needs easing.

Defect 12. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Laundry

Metal Windows/Doors - Fittings and Hardware

Material deterioration

The door lock/s have broken or are missing

May be a security issue

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Glazier



The window locking system is missing.

Defect 13. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Laundry

Cistern and Pan

Material deterioration

The pan is not secured adequately to the floor

If not secured there may be damage to the cistern

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plumber



The toilet cistern needs to be re-attached to the floor.

Defect 14. - Interior

| Defect Location: | Laundry |
|------------------------|---|
| Defect Summary: | Ceiling Nails Popping |
| Type of Defect: | Material deterioration |
| Description: | There are popping nails in the ceiling. |
| Ongoing Consequence: | Further nail popping. |
| Opinion of Cracking: | Not Applicable |
| Building Professional: | Note: This defect should be referred to a qualified building professional for the repairs/scope of work required. |

Building Professional Required: Plasterer, Painter



The ceiling nail popping needs repair.

Defect 15. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:



The fan and light switch need tightening.

Defect 16. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Bathroom 1

Ventilation (Interior)

Operational

The exhaust fan is not operating and the fan switch is loose and needs tightening.

Unhealthy allergens may develop

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Electrician



The exhaust fan is not operating.

Hallway

Ceiling Cracking and/or evidence of damage repaired

Damage

Cracking

Further cracking

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plasterer, Painter



The cracked ceiling sheet.

Defect 17. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Lounge Room

There are popping nails in various areas.

Material deterioration

The ceiling plaster joint is cracking and there are popping nails.

Further deterioration.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plasterer, Painter



The damaged plaster joint needs re-setting and the popped nails need repairing.

Defect 18. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Family Room

Metal Windows/Doors - Fittings and Hardware

Material deterioration

The door lock/s have broken or are missing

May be a security issue

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Glazier



The window has no locking system.

Defect 19. - Interior

Defect Location:

Defect Summary:

Type of Defect:

Description:

Ongoing Consequence:

Opinion of Cracking:

Building Professional:

Family Room

The skirting is missing and the timber architrave is swollen from water penetration.

Water penetration, dampness, Installation

The skirting is missing and the architrave is swollen.

Further deterioration.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Carpenter



The swollen architrave and missing skirting.

Defect 20. - Roof Void

Defect Location: Defect Summary: Type of Defect: Description: Ongoing Consequence: Opinion of Cracking: Building Professional: North Side, West Side, South Side, East Side Insulation Installation Insulation is incomplete Loss of insulation value Not Applicable Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plasterer



The roof void area has no insulation installed.

Defect 21. - Subfloor

Defect Location:

Defect Summary:

Type of Defect:

Description:

- Ongoing Consequence:
- Opinion of Cracking:

Building Professional:

The waste pipe under the shower.

The shower waste connection is leaking.

Water penetration, dampness

There is a leak under the shower in the subfloor.

Further leaking.

Not Applicable

Note: This defect should be referred to a qualified building professional for the repairs/scope of work required.

Building Professional Required: Plumber, Tiler



The shower is leaking around the waste point.

Defect 22. - Exterior

| Defect Location: | North Side |
|------------------------|---|
| Defect Summary: | The timber hand rails are unstable and are a safety issue. |
| Type of Defect: | Installation |
| Description: | The handrails are not joined on the timber post. |
| Ongoing Consequence: | Further deterioration of the handrail. |
| Opinion of Cracking: | Not Applicable |
| Building Professional: | Note: This defect should be referred to a qualified building professional for the repairs/scope of work required. |
| | Building Professional Required: Carpenter |



The damaged handrail is unstable and is a safety issue.

CONCLUSIONS

Other Inspections and Reports Required

It is recommended that the following Inspections and/or repairs/work required is obtained from the following trades and/or professions.

| Recommendations | |
|---------------------------------|--|
| Recommendations from the Report | Renderer. Plasterer Painter Carpenter Roof Plumber Glazier Plumber Electrician Tiler |
| Other Inspections Recommended | Electrical, Plumbing |
| SIGNED BY INSPECTOR | |
| Date: | 06/09/2022 |
| Signed: | |
| CONTACT THE INSPECTOR | |

If you have any questions regarding the report, please feel free to contact the inspector. It can be challenging to communicate defects, their severity, and any inspection limitations in a manner the reader can comprehend. If you have any concerns or require any additional clarification you should contact the inspector immediately before acting on this report.

Type of Defects

The definitions below relate to the Type of Defect associated with the building element/item fixture or fitting.

Damage: The building element/item fixture or fitting is damaged, cracked or broken and is not fit for it's intended purpose.

Distortion, warping, twisting: The building element/item fixture or fitting has shifted from its intended position.

Water Penetration, Dampness: Water ingress and/or dampness is found in unexpected or undesirable area(s).

Material Deterioration: The building element/item fixture or fitting is deteriorating due to rusting, corrosion, rot or decay.

Operational: The building element/item fixture or fitting does not perform as expected.

Installation: The building element/item fixture or fitting has not been installed as expected, is ineffective, unsuitable and/or has absent components.

Structural Defect: Weakness or departure from the expected structural performance of a structural building element.

Acceptance Criteria

The building will be compared to a comparable building of roughly the same age that has been constructed with the commonly accepted method at the time the building was built, and which has been maintained as expected so there has been no significant loss of strength and/or serviceability.

High: The occurrence and/or extent of defects exceeds the inspector's expectations when compared to a comparable building of roughly the same age that has been maintained as expected.

Typical: The occurrence and/or extent of defects is as the inspector anticipated when compared to a comparable building of roughly the same age that has been maintained as expected.

Low: The occurrence and/or extent of defects is lower than the inspector's expectations when compared to a comparable building of roughly the same age that has been maintained as expected.

Average: The overall condition of the building is consistent with buildings of roughly the same age. There will be some building elements that require some repair and/or maintenance.

Above Average: The overall condition of the building is above average when compared to a building roughly the same age. The building has been well maintained.

Below Average: The overall condition of the building is poor when compared with buildings of roughly the same age. There are significant defects to building elements requiring renewal, repair and/or maintenance.

Definitions

Accessible Area: is any area of the site and structures permitting safe and Reasonable Access to

perform the inspection.

Building Inspection Agreemnet: Shall be the agreement between the client and the inspector entered into prior to the inspection taking place. This agreement includes, but is not limited to, defined purpose, specific scope/areas of inspection, acceptance criteria and limitations. Should this report be transferred, the subsequent buyer of the property shall be bound by all terms and conditions of the Building Inspection Agreement, as detailed under Clause 11 of this Report. Providing the Buyer agrees to the terms of the Building Inspection Agreement, then they may rely on the report subject to the terms and conditions of the Agreement and the Report itself.

Structural Element: Physically noticeable part of a structure. E.g., Walls, including interior, exterior, and screen, Floors, Roof and Ceiling frames, Beams and Connections.

Building Element: Section or part of a building which, by itself and/or in conjunction with other sections or parts, achieves a characteristic function. E.g., supporting, enclosing, completing or servicing a building space.

Major Defect: A defect of significant extent where remedial works must be carried out in order to prevent un unsafe environment, loss of utility or further deterioration of the property and/or building.

Minor Defect: Any other defect that is not a Major Defect. **Note:** the inspector is not required to comment on individual minor defects and imperfections.

Safety Hazard: Current or pending serious safety hazard.

Residential Building: is a building or structure within the boundaries, under the main roof (including post initial construction). Includes Verandas constructed at the same time as the main dwelling. Alfresco under main roof. Attached and/or standalone structures containing habitable rooms. Retaining walls directly associated with the foundations of the Residential Building.

This Building inspection was conducted as follows:

- 1. in the case of a non-strata title property to comply with AS4349.1-2007 Inspections of Buildings;
- 2. In the case of a Community title or strata the Inspector did not inspect Body Corporate common property and the inspection will be limited to areas within the Lot or individual unit to comply with AS 4349.1-2007.

Terms, Conditions and Limitations

- 1. The report is not an "all-inclusive" report that considers the property from every aspect and is subject to the agreed scope of the inspection.
- 2. Unless noted otherwise, inspector conducted a visual, non-invasive inspection of the building elements only to the safe and accessible areas as outlined in the scope of the agreement.
- 3. The inspection is a reasonable attempt to identify major defects and safety hazards at the time of inspection.
- 4. The report is not a Certificate of Compliance with any Building Permit, Building License, Act, Regulation, Ordinance, By-law Standard or Code.

- 5. The report is not a warranty against problems arising in the future. Defects reported can further deteriorate or become a safety hazard if not attended to by a qualified professional.
- 6. Inspection on Strata, Company and Community title type buildings are limited to the interior and immediate exterior of the unit. It is recommended that the client review all available records of the Body Corporate including Maintenance Plans.
- 7. This is not a Structural Engineers Report. Where defects of a structural nature are identified, a Structural Engineers report maybe required.
- 8. Any Estimates Provided in the report are merely an educated guess by the inspector using their knowledge and experience to estimate the possible likely costs to be incurred. The estimate is not a guarantee or quotation for work to be carried out. It is recommended that independent quotes are obtained from trade professionals. The inspector accepts no responsibility or liability for any estimates provided.
- 9. The minimum space required for inspection is as follows:
 - a. beneath a floor vertical clearance not less 450mm;
 - b. exterior walls or roof and ceilings will only be inspected if it can be reached safely having regards to work and safety by use of a safe ladder which can be extended to a maximum of 3.6 metres from ground level;
 - c. roof void minimum access size must not be less than 450mm x 450mm with vertical space 600mm X 600mm for reasonable movement;
- 10. Not Included in the Scope of the Inspection:
 - a. Common areas of Strata, Company and Community title type properties.
 - b. Timber Pest Activity.
 - c. Presence or absence of mould.
 - d. Identification of ACM (Asbestos Containing Material).
 - e. Identification of flooring containing Magnesite.
 - f. Inaccessible or partly inaccessible areas.
 - g. Areas where access was denied.
 - h. Defects that may have been concealed.
 - i. Rising damp and water ingress (leaks) that maybe subject to prevailing weather conditions.
 - j. Water ingress (leaks) that are subject to services not being used for a period of time. i.e. shower recesses.
 - k. Technical assessment of electrical, gas, plumbing and mechanical installations.
 - I. Site drainage.
 - m. Swimming and Spa Pools.
 - n. Identification illegal building works.
 - o. Breaking apart and/or dismantling.
 - p. Removing or moving objects and materials included but not limited to vegetation, roof insulation, floor or wall coverings. Ceilings. Floors. Furniture. Appliances.
 - q. Removing or moving stored goods and/or personal possessions.
 - r. Impact to the buildings footings when trees are in close proximity.
 - s. Septic tanks.

- 11. Disclaimer of Liability: Compensation will only be payable for losses arising in contract or tort sustained by the Client named on the front of this Report. Any third party acting or relying on this Report, in whole or in part, does so entirely at their own risk. However, if ordered by a Real Estate Agent or a Seller for the purpose of auctioning, set date sale or private treaty of a property, then the Inspection Report may be ordered up to thirty (30) days prior to the auction, set date sale or listing, copies may be given out prior to the auction/sale and the Report will have a life of sixty (60) days from the date of Inspection during which time it may be transferred to the Buyer. Providing the Buyer agrees to the terms of the Building Inspection Agreement, then they may rely on the report, subject to the terms and conditions of the Building Inspection Agreement and the Report itself.
- 12. Complaints Procedure: If there are any claim and/or dispute arises with regards to the inspection and/or report you should inform us immediately by email. You must permit us full access to all areas of the property that relate to the claim and/or dispute. Within 28 days of receipt of your claim we respond to you in writing. In the event you are not satisfied with our response you must refer the matter to a Mediator nominated by us from the Australian Mediations Association Limited must within (21 days) from the date of our response. The parties shall bear equally the costs of the mediation. If you initiate court proceedings without observing the above Complaints Procedure and the proceedings are set aside, stayed or adjourned then you agree to be responsible for any costs and expenses incurred by us and you agree to keep us indemnified of such costs and expenses incurred by us.