

21st August, 2020

Guisepe Cardillo
83 Charlick Road
Crafers West SA 5152

Re: Letter of Compliance

I have carried out an inspection of the pool safety barrier at your property of 83 Charlick Road, Crafers West 5151 on the 21st August 2020.

Your Pool safety barrier is compliant and no further follow-up is required.

The checklist below was used for the inspection and is based on the Australian Standard AS1926.1- 2007. The assessment is based on the assessor's knowledge of the statutory requirements and Australian Standards, and is limited to the observations made at the date and time of inspection.

POOL FENCE	Yes	No
Fence height min. 1200mm	X	
Wooden Fence in good condition	X	
Vertical members – gaps 100mm or less (actual 97-100mm)	X	
Horizontal members spaced 900mm or more	X	
Gap under fence less than 100mm	X	
Non climbing Zone outside fence 900mm applies	X	
Glass Fencing min. 1200mm	X	
Gap under glass panels less than 100mm	X	
STRENGTH & RIGIDITY		
Strength & rigidity of Wooden uprights expand to max of 105mm	X	
Strength & rigidity of posts and footings – any deformation or breakage		X
Strength & rigidity of rails – any deformation or breakage		X

Cont'd

GATES x 2 (1 wooden and 1 glass)		
Wooden gate height min 1200mm	X	
Glass height min 1200mm	X	
Gate release mechanism min height of 1500mm from ground	X	
Gate release mechanism min height of 1400mm from top of lower rail	X	
Gate release mechanism is located inside gate min 150mm below top of glass gate	X	
Gate self-latching from three stationary positions (carried out on both gates)	X	
Gap under gate less than 100mm	X	

Inspection Date: 21st August 2020

Time: 11.00am

Inspected By: David Hutton

If you require further information about this assessment, please contact me on 0424 711 963.

Yours Sincerely,

David Hutton

Director