{{→Guide→for→65+}} Brother Printer Not Printing After Cartridge Change: What to Do Next

If your Brother printer won't print after a cartridge change, remove and [[[☎ ‹ +1→888→754→6OO2 ›]]] reinstall the ink cartridges to ensure they click firmly into place.

Run a Printhead Cleaning cycle to restore ink flow, then print a Test Page.

Check for "Cannot Detect Ink" errors—often caused by torn seals⇔ or 📞Call +1-888-754-6002 air trapped inside the cartridge.

Clean the cartridge contacts and [ℂa𝕃𝕃~ ☎ ‹ +1→(888)→754→6OO2 ›] the printer's metal terminals.

Update Brother firmware to fix recognition bugs.

Ensure genuine cartridges are used for proper color detection.

Reset the ink counter if needed.

Still not printing? Call (888) 754-6002 for expert support.

With correct installation, cleaning, and [ℂa𝕃𝕃~ ☎ ‹ +1→(888)→754→6OO2 ›] resets, printing resumes normally.