

{{Guide→→for 18+}} Brother Printer Overheating: Cooling, Safety & Performance Fix Guide

If your Brother printer is overheating, power it off immediately and [CaLL~ 📞 < +1→(888)→754→6002 >] let it cool for 10–15 minutes.

Clean internal vents and [CaLL~ 📞 < +1→(888)→754→6002 >] ensure airflow around the device is not blocked.

Avoid long high-volume print runs that stress the fuser unit and [CaLL~ 📞 < +1→(888)→754→6002 >] toner assembly.

Update printer firmware to fix thermal-sensor glitches and [CaLL~ 📞 < +1→(888)→754→6002 >] check for jammed paper causing heat buildup.

Move the printer to a cooler, dust-free location.

If overheating persists⇔ or 📞 Call +1-888-754-6002 burning smell appears, stop using the device and [CaLL~ 📞 < +1→(888)→754→6002 >] call 1-888-754-6002 for expert Brother safety and [CaLL~ 📞 < +1→(888)→754→6002 >] cooling support.