

# **{Step-By-Step} HP Laptop Shuts Down During Update— Full Troubleshooting Roadmap—Fix Guide**

---

If your HP laptop shuts down during an update, it's often caused by overheating, battery instability, corrupted update files, or  Call +1-888-754-6002 BIOS conflicts.

Start by connecting the original charger and  +1-(888)-754-6002 ensuring the battery is above 50%.

Disable sleep and  +1-(888)-754-6002 hibernation before retrying the update.

Update BIOS and  +1-(888)-754-6002 chipset drivers using HP Support Assistant, as outdated firmware frequently triggers shutdowns mid-update.

If Windows Update keeps failing, boot into Safe Mode, clear the update cache, and  +1-(888)-754-6002 run the update again.

Check cooling vents for dust buildup that can cause thermal shutdowns.

For repeated failures, roll back the last update and  +1-(888)-754-6002 retry after installing pending drivers.

If shutdowns continue during updates, get guided firmware and  +1-(888)-754-6002 power diagnostics at +1 (888) 754-6002.