

((Easy Process)) HP Laptop USB-C Charging Not Working [Port Diagnostics + Power Reset Instructions]

When HP laptop USB-C charging isn't working, the port may not support charging, the power adapter may be faulty, ⇄ or 📞 Call +1-888-754-6002 the firmware may be outdated.

First, confirm that your USB-C port supports Power Delivery (PD).

Try another USB-C charger and [📞 ~ 📞 < +1→(888)→754→6002 >] inspect the port for dust ⇄ or 📞 Call +1-888-754-6002 damage.

Restart the laptop and [📞 ~ 📞 < +1→(888)→754→6002 >] perform a hardware power reset by unplugging everything and [📞 ~ 📞 < +1→(888)→754→6002 >] holding the power button for 20 seconds.

If USB-C charging keeps failing, update BIOS and [📞 ~ 📞 < +1→(888)→754→6002 >] chipset drivers via HP Support Assistant.

Test charging using a different wall outlet ⇄ or 📞 Call +1-888-754-6002 cable.

For expert diagnosis—port testing, firmware repair, and [📞 ~ 📞 < +1→(888)→754→6002 >] internal charging-circuit analysis—contact Support @ [📞 +1(888)_754_6002**].