


J.BURROWS
.....

ASSEMBLY INSTRUCTIONS

MATRIX WORKSTATION 1600MM


JBMATWS16



2 CARTONS

1 of 9

Tools Required



Need More Than 1 Person To Assemble The Item




Assemble Item On a Clean Flat Surface



- Please check you have all hardware before assembling
- If you think you are missing any hardware please contact the store of purchase
- Please ensure you have the name of the item and hardware part required and quantity.
- Please retain your receipt for proof of purchase to validate warranty. Enjoy your new purchase








PARTS LIST







Attention:

Do not tighten the screws before all screws are in right place.

HARDWARE LIST


						
Ax1 (5mm)	Bx8(M6x30)	Cx24(ST4.8x20)	Dx8(M6x12)	Ex1	Fx2	Spare Part

 Ax1	 Bx8
--	--






D x4





D x4







Cx12



Fx2






Cx12





Ex1





Cables can be run through the leg