
Matrix mesh medium back Assembly instructions

Need Help!
Assembly Videos on
www. pagointernational. com. au
E:sales@pagointernational. com. au

2 1. Insert the back firmly into the mechanism at the back of the seat unit. 2. Push down all the way until the back bottoms out. 3. Lift the back slowly through the rachet slots until the lumbar is in the correct position. 4. If you raise the back beyond the top rachet slot, go back to point 2







Pago International Pty Ltd

ABN: 40 613 903 816

Warranty 15 years

Product Warranty – valid for Australian customers only

Pago International Pty Ltd warrants that this product will be free from defects and work as intended for 15 years from the date of purchase by the original customer. If the product has any defects or does not work as intended during the Warranty Period, Pago International Pty Ltd will, at its election and at its expense, repair or replace the product. This warranty does not apply:

- to cosmetic damage.
- to damage caused by consumables used in connection with the product (such as
- cleaning products).
- where the product has not been used in accordance with all provided instructions.
- to damage arising from fair wear and tear.
- where the product has not been subject to reasonable use.
- where the product has been intentionally or negligently damaged; and/or
- if the customer has attempted to repair the product.

To make a claim under this warranty, please return your product with your receipt or proof of purchase to your nearest Officeworks store or contact 1300 633 423.

This warranty is provided in addition to any rights you may be entitled to under the Competitions & Consumer Act 2010.

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.