

Product Safety Recall



Serial number

Ark Tow Ball Mount

TBH160, TBH160D, TBH190, TBH190D, TBH280,
TBH280D, TK160C, TK190C

Serial no.'s A177 to A190. Sold Oct 2014 to May 2015

Defect In some circumstances the tow ball mount may break at the bend just behind the tow ball.

Hazard If the defect occurs whilst towing this may result in the towed trailer or caravan separating from the tow vehicle and causing a possible accident hazard to the vehicle occupants and other road users.

What to do Consumers should immediately stop using the tow ball mount and return it to the place of purchase for a refund or replacement.

Contact details Contact Ark Corporation by phoning 02 9678 9036 Mon-Fri 9am-5pm or via email sales@arkcorporation.com or go to www.arkcorp.com.au

**See www.recalls.gov.au for
Australian Product Recall Information**