AWM4


Australian Imperial Force unit war diaries, 1914-18 War

Engineers

Item number: 14/7/16

Title: Headquarters 1st Australian Divisional Engineers

April 1917



AWM4-14/7/16

INTELLIGENCE SUMMARY.

(Erase heading not required.)



Army Form C. 2118.

333

Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
BAISEUX	121		Decided to allot 1/2 7. Co. track brigade as soon as we go into the line. Went on	
	45		to Corps H.Q. and interviewed the C.E. is allotment forgineers when we go into new	
			area. 1st field Company are still with amar higher Kailways. Lander the agreet	
			waste of technical library as they are usually only used as plate layers, stone breaken	
			F- and not to superiors working parties.	
do	214		Instruction sent to 2" & 3" Hos to get in touch with their respective Brigades	
			3rd y per Respectively and to assist in the building of their H.Q. I Company of the Provider	
			surrupt Bancourt trassist in the buildy frew SHQ.	
do .	3-1		Office work and squaring up preparating to going up to hew the tomorrow.	
1.	4#		went up to new AHR, hear Bancourt and found satisfiely purgess being made in creation of huto, cannonflage ster went never to 5th aust Dir! to see CRE re	
			in crection of huto, cannonflage ste. Went aum to 5th aust Dw! to ser CRE re	
Bancourt			titing our line of.	
ello	5t		went aum to 5th aust Din HQ, and arranged with CRE 5th div. 18 dumps 15	
			A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2113/13.	peach.

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

INTELLIGENCE SUMMARY.

(Erase heading not required.)

H.Q., 18T MUSTRE L'AM

Army Form C. 2118.

Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
BANCOURT	5th		Very little to take one as there are no proved dump.	
	6		hent acros to Fremiconst and 3rd Lif Bols are 2" 7-60. also inspected chain	
			Helice pump on well at Fremiens are awayed forthe improvement of the	
	7t-		hater point. Went auros to 3rd Field Coy's camp near Bancourt and then side out wint major	
			Savage along the word to Haplincourt and then across to Delsaux Farm when I saw 9.00. P. Inf Bds. Returned vin Bengay and the main Barpaume Cambrai	
			Road. Theroads are generally in fair condition and work of improvement is	
			proceeding steaduly.	
	8-		Regular working parties have been put on to put the Baparene - Campai Rd in	
			order under the Rupeirson of 2rd Field Cay. The portion of the road in this Dry auca	
			is very good except for the trulers. beent up at 10 am, to impect the works	
			Parties found everyth sutespectory agrost purpers ten made. " eller	20

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

or

INTELLIGENCE SUMMARY.

Army Form C. 2118.

27

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

(Erase heading not required.) Kemarks and Hour Place Summary of Events and Information references to Appendices also inspected the trado through furnioned which she great improvement. In afternoon went to Villers - an Flore is sheller for Mobile Vet Section & to hymatery strong points & & Memahon killed by shell fire. bent not though Haplement to Berlincom then acom to Vile Lebriquiero. Found the roads in Janely good condition. went up to the Bengny - This line with Gen. Lotonier of al Blamey. the left and then right along to Delsoux farm matter some distance beyond Line in fairly good ode and let of work has been done onit. A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2113/13.

02

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

INTELLIGENCE SUMMARY.

(Erase heading not required.)


H. Q.,

1ST AUSTRALIAN
DIVL. ENGREETIS.

No. 184 6 308

Date. Gene 190

Army Form C. 2118.



Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
Barrent	一		went not to delsaux 7ms an other on to Beaumity an imperior the site for	
			Bas H. Q. v advanced Div. H.Q. ass	
	124		This company is again being bookly handled by the # 2. R. and are not only not	
			dog begittimate held tog work but are being humbagged in bothert they are	
			doing. There repeatedly protested against a trolding my allotted with 15th	
			as it is a wasto of technical labour but apparently with care the and as	
			the Ot ALR apparently does a belike.	
	13th		all day in Office her site has been selected at searners for said this	
	14		went up to Beaumets with Ath Henderson & Capt. Bollon of Pronews and maperted pite for new Ede HD. in a drep sunker Rd. arranged friends to	
			magneted site for new Ede HD. we a drep sunker Rd. arranged frunklo	
			stur the tomorns.	
			A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2113/13.	+

or

INTELLIGENCE SUMMARY.

1ST AUSTRALIAN
DIVL. ENGL. LRS.

No. 1804 to 26 9

Date. Garil 1917

H. Q.,

Army Form C. 2118.

023

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

(Erase heading not required.)

will be prepared in manuscript.			(Erase heading not required.)	
Place	Date	Hour	Summary of Events and Information	*Remarks and references to Appendices
Barcont	15#		bout up to Right of Corps Line between Hapliniant or Bectinismit with C.E. Playar	
			where we met C.S. 15th Tops and decided on boundary line ste between the two app	
			Corps.	
	16th		CRX 4th aut Dir. came in almo 10 am. and we discussed question of which in	
			Beaumity Line. arranged for 12th 46 to get Beugny brunk in left and	
			1 to by to Vil. touch a right bent out to Fremioner when I saw	
			200 Flo. Men on 8 3r. flo. at Isturginers. Them rode out to the canal	
			& maspeeted fortbridge 3". Has put om last night.	
	17		Ch horte	
	It		In the Bale Ha When I saw matter or 2" Ito are discussed juntimes	
	182		Award at with Soc 2 Bde, Went on up to Beaumets and inspected new Bde.	
			Junk st unt Soc 2 Bde, bent on up to Beaumets and inspected new Bds. HO in course of construction. Olso sow 12th 44th Flos, re their work on A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2118/13.	
			A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2118/13.	07

or

INTELLIGENCE SUMMARY.

H. Q.,

1ST AUSTRALIAN

DIVL. ENGLICERS.

No. 105 & 30 4

Date. Cypril 1912

Army Form C. 2118.

023

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

(Erase heading not required.)

WIII DE	prepared	in manus	(Erase heading not required.)	
Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
Bancourt	18/2		Beaumety Line. I see no particular warm for importing any detaile of too to do this work. If we were not deprived of posto or 2 Corps of Promises on all the in shorted have plant of labour to meet all interpresses are here taken yesterday. The division is the working thrist and all himsemial twoops should be lift with the Divisions and the Corps work is required it should be tone by the Divis as a contract. The septem of letaching writes as at present is very wastiful platons and extremely unsatisfaction are care only lead to dissister. Up to the present, although 17 to 72 Provins Bres are worky for ALR, the line has not carried anyth except communition and has practically been plittle or my use to the Division.	
			A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2118/13.	0

orINTELLIGENCE SUMMARY.

(Erase heading not required.)



Army Form C. 2118.

Instructions regarding War Diaries and Intelligence	or
Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages	INTELLIGENCE SU
will be prepared in manuscript.	(Erase heading not requir

Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
Bencomt	18/1		wentup to Fremionit was 2" FCo. there on to 3" FCo. at I struginers are the went went wind the posts on the Beagage Beaumet, Line must major Savage, Hardie & Tollow. Also went some Doigneis & decided on position for Strong Points.	
	1		at the went round the posts on the Beargay Beaumety Line most major Savage,	
			Hardie & Tolley. also wentrome Doignies & decided on position for Strong Pointy	W .
	20th		oproble.	
	2135		Rode up to 2" I.Co. and then to Sir dump trees that wire unique out all	
			right. CRE-11th Dir. came in dung afternoon to make pretion unexpensent	
			In takin orm.	
	227		bentup to 2" I.Co. and then out with hap mathe to Marchies a went some the line	
			of posto. agood deal from is you needed to make the posto really good.	
			Then were on to Branning an saw with m new Bods 14th, & called in to see	
			the Bda.	
	23-		Spent morning an Office. Leaflermon Instantia no with CRS. 11th Din " are all	M. T.
			Spent many au Office. Leaflern Laterted not writ CR8. 11th In " are priseted 200 HG at Fremionis the map to Laboreginess to 30 HG. Then went A5834 Wt. W4973/M687 750,000 8/16 D. D. & L. Ltd. Forms/C.2118/13.	~1

or

INTELLIGENCE SUMMARY

1ST AUSTRALIAN

DI.L. Ein. S.

184 & 204

Bate. April 1917

Army Form C. 2118.

023

Instructions regarding War Diaries and Intelligence Summaries are contained in F. S. Regs., Part II. and the Staff Manual respectively. Title pages will be prepared in manuscript.

(Erase heading not required.)

Place	Date	Hour	Summary of Events and Information	Remarks and references to Appendices
Sancont	234		went out to Right Flank of Beaumity him amigeted posts right back to	
			Beaumity. bent mer to Bale Hill is then accord to tambai Ka is back	
			though Bengy.	
	24		Spent the day aguary up office work preparatory to handing on to 11th abir!	
			CRE 11th Dir. came om at Ethanded om to him maps x. I had ready	
			The ot C. Freld ling came in dung the every to discum various matters. eggs	
	25%		Completed having towar to 11th Drive went out with Gen. Lolbinion are inspected the Bengang Line 2" & 3" Files how works on Bengang line.	Handing over
			the Bengny Line 2" & 3". F. Cos mo worky on Bengny line.	179
	26"		Office work.	
	37/2		office work.	
	一大		Visited 2nd dust this is covered matters.	
	28-		Rode ont to 3rd Lto to inspect their camp , to riginie int defences of Haplement &	
	29%		hent to Bonginian to be a line with supply	00 00

HANDING OVER REPORT - Right Brigade Area.

1.FRONT LINE SYSTEM.

The Front Line consists of several strong points and a line

of outposts.

There are strong posts at K.25.b.9.2. K.14.a.1.3.

K.13.b.7.9. K.7.d.4.4. K.7.0.9.5. K.7.b.5.0. J.12.b.9.3.

J.6.c.6.6.

Most of these strong points are Y form as below,

capable of holding 30 or 40 men and are about 50 yds long.
Each strong point has at least one M.G. emplacement and in

some two. They are constructed so that they cover all approaches in their vicinity and give supporting fire to the line of outposts.

The outposts originally could hold four men but they have been enlarged since and most of them can hold at least 12 men and several of them 20 men.

The whole of the ground in front of the front line is covered by rifles along the strong posts and outposts and by M.G. placed in the Strong Posts.

There are about 25 outposts in the line and about 600 yds

of rifle pits along Sunken Roads in front of DEMICOURT.

The outposts are in a fair state at present but require

firestepping and widening

anything from 20 yds to 50 yds long and total about 1200 yds.

Plain wire has been laid between all posts to guide men from one post to another.

There are no communication trenches and it is not possible to walk between posts during the day.

There are no dugouts in the front line with the exception of one or two shelters and shelter is very poor.

WIRING. Wiring has been done in the most important places

K.20.c.3.9. about 100 yards. K.20.a.2.3. about 80 yards. K.14.c.2.2. about 100 yards. K.7.b.5.0. about 430 yards.

J.6. about 480 yards.

Total wiring is 1190 yards and at present consists of one row of French concertina wire.

Accomodation for Bn.H.Q. and troops.

Battalion Headquarters are small dugouts in Sunken roads with splinter proof roof.

Troops are camped in small dugouts along the sunken roads in rear of their battalion and in a few rear trenches.


2. BRIGADE RESERVE LINE. .

This consists of ten strong points at

/ J.14.b.0.8.

377

2. BRIGADE RESERVE LINE. (Contd)



capable of holding 90 men each. From J.22.c.0.5. to J.34.b.5.3. there is a continuous line of French concertina wire with a barbed wire apron fence thus

and J.15.c.3.1. is wired.

ACCOMODATION. No dugouts in the posts at present but dugouts could be built as material comes along.

3. Accomodation for Brigades and Battalions etc.

Brigade Headquarters is at J.20.c.8.3. BEAUMETZ. This is a new Headquarters and is now almost complete. Attached plan shows the accomodation proposed, the coloured lines showing the completed work. The position is in a deep sunken road, which has been camouflaged overhead. The bank excavated and huts as shown put close up against it. There are four tarpaulin covered huts with boarded floors, three Armstrong huts and cook houses. The dugout accomodation consists of three stairways with connecting gallery between. At foot of each stairway is a 9' x 6' cubicle with 24' headcover. The dotted lines show the proposed cubicles for additional accomodation which would have been completed had the Division been staying in.

Left Bn. Headquarters is at J.17.a.8.7. and is dug into the side of a sunken road and has a splinter proof roof. There is also shelter in road for 250 men.

Shelter for 150 men along road J.12.a.1.8 to J.12.a.6.7.

Shelter for 150 men along road from J.6.c.7.7. to J.12.a.7.8.

Centre Bn. Hea quarters is at J.22.b.9.9. and is a dugout on side of sunken road with splinter proof roof.

Shelter for one company in road near Bn.H.Q. and in trench running beside road.

Shelters for one coy. in road from J.12.c.5.1. to J.18.a.9.9.
Right Bn. Headquarters is at J.29.c.5.4. near old brick kiln in a splinter proof dugout.

Shelter for one company along line in front of HERMIES from J.24.d.5.8. to Canal Du Nord.

4. WELLS.
Wells fit for drinking purposes are at following map locations:

/ 3.14.0.3.4.



- 3 - Right Bri ade Area Contd.

4.WELLS.(Contd.)

J.14.0.3.4. BEAUMETZ. J.16.b.3.5. DOIGNIES.

J.25.2.3.4. VELU Railway Station. J.6.C.7.8. BOURSIES.

Water level in these wells is about 100'.

No pumps are being used at present, windlasses only. At present a power pump at the well in BEAUMETZ J.14.c.5.4. and at VELU Railway Station would be of great value.

5.BRIDGES.

Foot Bridges are across the Canal at the following places:-

J.34.d.9.7. J.35.cent. J.35.b.7.0.

and will carry infantry in single file ONLY.

6. DEFENDED VILLAGES.

HERMIES.

Is defended by a line of small fire pits from J.36.b.0.6. to J.30.d.7.4. capable of holding about 100 men.

A Strong point at J.50.d.8.7. capable of holding about 30 men. (About 80 yards of barbed wire around this post.)

A Strong point at J.30.b.7.7. capable of holding about 30 men. (About 50 yards of barbed wire around the post.)

A Firing line from K.28.2.0.5. - K.19.c.2.0. - K.19.cq.7. -

J.24.d.5.8 .. Capable of holding about 400 amen.

A line of small fire pits from J.24.8.5.8.to J.24.a.7.5. holding about 50 men.

DOIGNIES.

A Strong Point Y type under construction at

J.16.b.5.2. . J.16.b.9.6.

J.16.b.8.8.

J.10.0.9.4.


J.16.cent. 150 yds fire trench dug. at.

these posts are about 5'8" deep and 3' wide and have not yet been completed. (Accomodation in tranch mil at present).

7. MISCELLANEOUS.

At P.4.a.7.7. at the western end of slag heap a road across a depression is under construction.

(Plan on Page 4. Right Brigade area).



Appendix No.1

24th.April 1917.

DIVL. ENGINEERS.

13

377

HANDING OVER REPORT , Left Brigade Area.

1. FRONT LINE SYSTEM.

This consists of a line of cutposts, and a number of strong points in rear of them. The outpost line consists of a series of short disconnected trenches each 20 yds to 40 yds in length and 3' to 5' deep. In most of them there is weatherproof cover for the garrisons, which may vary from 1 platoon to platoon. There is a small amount of wire in front of each picquet posts in most cases consisting of 1 row of German concertina barbed wire. In some cases a rough single apron fence is constructed of corkscrews and barbed wire. The positions of these posts are shewn on map, and their general sutking form is thus:

only the deeper ones are firestepped.

Behind these posts are Strong Posts whose location is shewn, mumbered from 1 to 12 on the map. The general form of these is as shown on attached Type Plan. Of these Nos. 5. 6.8.9.10.11 are dug, but more work is needed to complete the digging.

Nos. 1.2.4. and 7 are pegged, but not dug. No.5 has yet to be pegged. No.11 and 12 and 10 are well wired but there is no wire out at the others except No.6., where some German wire is utilised. All the strong points shown as dug, are down to a depth of just over 3 a nd should be deepened to allow of full depth of 5 and fire-step.

2. Brigade RESERVE LINE. Beaumetz - Morchies Line.

No.1 post at J.8.c.9.2. 100 yards of plain fire trench 4' deep, 5' wide, flanks bent back a little. Barbed wire apron erected over one row of plain French wire; extending over front of work and bent back slightly at flanks.

Recommended. (i) Left flank should be extended back to ditch alongside main road to facilitate communication. (ii) Whole work should be deepened a little and widened a lot, as the narrow trench would be completely blocked if a shell were to strike it. (iii) Wiring should be extended round both flanks further.

No.2 Post at J.8.c.4.4.

50 yards of plain fire trench 5'6" deep, 2'6" wide, with wings

bent back. Wire: - 1 row of French concertina wire covering front and slightly bent round flanks. M.G. post on right flank. Recommendations: (i) Good communication to road at rear to be provided. (ii) Wire to be thickened by another row of French wire and loose barbed wire. (iii) Whole trench deepened and widened. (iv) Position for M.G. should be provided and connected up, on right flank.

No.3 Post. at J.8.c.2.6. 100 yards of fire trench 4' deep 2'6" wide flanks turned back and connected by communication back to sunken road from right flank. Communication trench far too sum narrow and not deep enough. One line of French wire out.

Recommendations: (i) Left flank to be turned back further and connected to sunken road by communication trench. (ii) Trench to be deepened and widened. (iii) Wiring to be increased and low wire (trip) to be placed in an excellent hollow which runs parallel

to the work about 50 yards in front. Post No.4 at J.7.b.0.7.

100 yards of fire trench 4' deep and 2'6" wide. Wire: 1 row of French concertina over the front of the post. M.G. pesition on Right Flank. Recommendations: — (i) An extension to the left flank has been made which **mexemetrather prevents the effective fire from the left wing of the original work. This should be either filled in, or the left flank of the extension should be carried back so as to allow to be given up the hill to the left. (ii) Whole work to be deepened and trench widened. (iii) Wire to be improved. (iv) Communication trench to be run down from sunten road to left flank of this work.

377

2 = Left Brigade Area Contd.

2. BRIGADE RESERVE LINE. (Contd.)

No.5. J.1.c.2.0.

100 yards of fire trench with wings turned back, 4' deep 2'6" wide.

Wire. 1 Line of French wire over front of post. Recommendations:
(i) Deepen and widen trench. (ii) Bend the flanks further back

on each side. (iii) More wire. (iv) Communications of some kind.

This will be somewhat difficult, as this work is on a forward slope

with no sunken road or depression for a long distance to rear of

it, but as the post would only be ranned during an emergency, this
is not of such vital importance, as the men would then be available

to dig long communications.

No.6. Post I.6.d.6.6.

100 yards of fire trench 4' deep 2'6" wide, flanks bent back.

One row of French wire, and few strands of barbed wire across
front of post. Recommendations: (i) Flanks of trench to be
bent further back on both sides, so as to support neighbouring
posts better. (ii) Deepen and widen trench. (iii) Increase
wiring. (iv) Put in M.G.positions. (v) Dig communication from
sunken road at I.6.b.8.7. alongside road, like a drain, towards
Ho.6 Post leaving just the road to be cut through in emergency.

No.7 Post. I.5.b.7.6.

100 yards fire trench 4' deep 2's" wide. Half the front is covered by one row of French wire. Recommendations: (i) Deepen and widen trench. (ii) Increase wire. (iii) Make a communication from left flank to ultimately gross the road and establish a post on high ground in rear of crucifix in trees, then communicate to sunken road at I.5.b.6.6. (iv) M.G.Positions.

No.8. Post. I.5.d.4.4.

50 yards fire trench 3'6" deep, 2'6" wide. Wire nil.

Recommendations: (i) This post badly sited and might well be left
out of the scheme. (ii) It time admits it could be connected
to sunken road in rear, and wired so as to ask form an extra post for
immediate defence of MORCHIES.

No.9. Post I.5.c.6.7.

100 yards fire trench 4' deep, 2'6" wide. Single row of French wire. Recommendations: (1) Deepen and widen trench. (ii)
Dig good communications back from flanks of work to sunken road which gives excellent cover for garrison. (iii) Complete the wiring of the post. (iv) There is one M.G. position but more are needed.

No.ROPost 1.5.c.2.8.

50 yards of fire trench 4' deep 2'8" wide. Wire nil, but some on site. Recommendations: (i) Widen and deepen trench.(ii) complete wiring. (iii) Cut the communications back to sunken road.

No.11 Post I.4.d.8.8.

80 yards fire trench 4' deep 2'6" wide. One line of French wire.
Recommendations: (i) Extend the post by running the flanks back
to the rear further, especially the left flank, which should
follow along parallel to the road on the left of the work.

(ii) Put in M.G.positions. (iii) Complete wiring.

Posts were originally for 60 rifles but some are more, others less. Suggested that M.G. position should be selected and established in MARICOURT WOOD (Forward side) to cover a little dead ground in the valley in front.

A good Brigade Headquarters has been built at I.ll.c.8.8., and has been found to give the necessary amount of accomodation.

A temporary Headquarters is being fixed up at the sunken crossroads at 0.29.2.4.2. This is an excellent site for a Brigade Headquarters, the banks of the cutting in parts are as much as 20' high above road level. A week's work would suffice to make a splendid headquarters.

- 3 - Weft Brigade Area. Contd.

Well at I.5.d.5.0. Water at 60' and 6'to 8' deep. Windlass on site. Pond at I.11.b.5.9. May be used as water point for animals.

Well at I.5.d.8.3. Water at 50'. Depth 8'. Windlass in good order. Power pump could be used here.

Well at I.5.d.9.1. Water at 65'. Depth 15'. Windlass fitted and in good order. Power pump could be used.

Well at I.22.a.2.5.BEUGNY. Mukkxxk water at 90'. Depth 15'. Windlass in good order. Power pump could be installed.

Well. I.23.d.82.8. LAGNICOURT. Water at 60'. Depth approx.8' of good water.

Well. I.25.b.3.8. Fremicourt. Water point. Chain-elice pump. Tanks constructed.

5.BRIDGES. Wil.

6.DEFENDED LOCALITIES.

This village is defended by a set of strong points shown on map as No.9.10.11.12 and another at C.23.b.5.8.

The posts are also as per Type Plan attached, and there is a belt of two rows of French concertina and barbed concertina wire extending right across the front of Lagnicourt (total lineal front 1300 yards) with gaps between posts for our troops to get out to the forward line and back. There is also a M.G.Position in a small trench at C.18.c.1.2.

This village's chief defences consist of rifle recesses cut into the sides of the sunken roads at J.4.a.5.9. and J.4.b.2.2. Also a good bank with some shelters and rifle recesses exist at J.10.a.9.9. Strong posts are sited at J.5.a.3.1., J.4.b.4.6., D.28.c.6.2. and J.5.b.2.2. which will cover Louverval. Of these No.3. and 4 are partially completed but No.1 and No.2 are only marked out. There is no wire in front of Louverval except on outpost line.

This village is defended by strong posts Nos.5.6.7.8.9. shewn on map. All these posts are dug ro an average depth of 3'6" and all except No.8 are wired with a single row of French wire. In addition to these strong points there are excellent sunken roads across the front of the village and also running out from the centre of the village to the flanks, which makes a perfect natural defence.


7.MISCELLANEOUS.

Brigade Area dump is situated at I.17.d.5.5. It consists of sandbags, barbed and french wire, corkscrews, and C.I.

The demand for material has been greater than the supply so that dump is practically empty.

A small salvage dump was formed by 2nd. Field Company A.E. in BEUGNY at I.16.c.7.0. Almost the whole material salved has been used, and a great deal of material used at Bde.H.Q. at I.11.c8.8.

Material is obtainable from ruined villages.



AUSTRALIAN WAR MEMORIAL