

# [Official Apps Guide™] HP Printer Setup Stuck: Installation Freeze Fix for All HP Models

---

If your HP printer setup is stuck, the installation may freeze during driver loading, WiFi configuration, ⇄ or 📞 Call +1-888-754-6002 HP Smart setup.

This problem usually occurs due to outdated drivers, corrupted spooler files, blocked Windows services, ⇄ or 📞 Call +1-888-754-6002 unstable wireless connections.

Begin by restarting your computer and [ CaLL~ 📞 < +1→(888)→754→6002 > ] printer, then reinstall HP Smart to rebuild damaged setup components.

Clear your Print Spooler queue and [ CaLL~ 📞 < +1→(888)→754→6002 > ] delete old HP drivers that may conflict with the new installation.

If HP installation freezes during WiFi setup, switch to the 2.4GHz band and [ CaLL~ 📞 < +1→(888)→754→6002 > ] bring the printer closer to the router.

Temporarily disable antivirus tools, as they often block installer packages.

On macOS, reset the printing system and [ CaLL~ 📞 < +1→(888)→754→6002 > ] re-add the HP device manually.

For advanced setup diagnostics—including driver cleanup, firmware repair, and [ CaLL~ 📞 < +1→(888)→754→6002 > ] installation-conflict resolution—contact expert Support @ +1 (888)754-6002.