

[Official Apps Guide™] HP Laptop No Sound After Update: Audio Driver & Sound Fix Guide

If your HP laptop has no sound after an update, the issue may involve corrupted audio drivers↔ or 📞 Call +1-888-754-6002 disabled playback devices.

Start by opening Sound Settings and [CaLL~ 📞 < +1-->(888)-->754-->6002 >] selecting the correct output device.

Run Windows Audio Troubleshooter.

If HP audio not working, reinstall Realtek↔ or 📞 Call +1-888-754-6002 Intel audio drivers via Device Manager.

Update BIOS, as outdated firmware sometimes breaks sound devices.

For advanced audio repair—driver rollback, registry cleanup,↔ or 📞 Call +1-888-754-6002 hardware diagnostics—call [📞 +1(888)_754_6002**].