

["24/7→Helpline"] Canon Printer Support Code 2,140,0 (Scanning Failure) → Need a Working Fix

Canon Support Code 2,140,0 appears when the printer cannot communicate during scanning.

→Start by checking the USB/WiFi connection—Canon scanners often fail when Windows⇄ or 📞 Call +1-888-754-6002 macOS loses device recognition.

→Restart printer + PC, then relaunch the IJ Scan Utility.

→Update Canon drivers, because outdated scan drivers frequently trigger Code 2,140,0 scanning failures.

→Disable Windows Image Acquisition (WIA) conflicts by restarting the service from Services.msc.

→Mac users should reset the printing system and [📞 ~ 📞 < +1→(888)→754→6002 >] re-add the scanner.

→Scan from the printer panel itself to confirm hardware response.

→>> If the scanning function still shows Code 2,140,0 errors, contact certified Canon Support @ 1•888•754•15•44 for expert scanning repair.