




ASSEMBLY INSTRUCTION
OTLINWSTN
LINEAR WORKSTATION (2CTNS)



Important


Estimated Assemble Time: 45min



MORE THAN 1 PERSON
IS REQUIRED TO SAFELY
ASSEMBLE THE ITEM



HOTLINE



ASSEMBLE ON A CLEAN,
FLAT SURFACE

Please check you have all hardware components before assembling.


If you are missing any hardware components from the Hardware List please contact My Zone on Tel: (03) 9310 3011, or Email: hardware@myzone.net.au

Please ensure you have the name of the item, store purchased from, hardware part required and quantity.

If you are missing any panels from the Panel List please contact your store of purchase.


Please retain your receipt to validate warranty. Enjoy your new purchase!

Panel List




Hardware List

A




Ø7.8 X 30mm
26pcs

B




Ø8 X 100mm
6 pcs

C




Sticker
6 pcs

D




1 pc

E




6 pcs

F




6 pcs

G




6pcs

H




1 pc

I




Ø6 X 50mm
20 pcs

J



1 pc

K



1 pc









L



Ø3.5 X 12mm
4pcs









Step 1

Note: Do not tighten the screw B fully until you have completed Step 5!







Step 2





Note: Do not tighten the screw B fully until you have completed Step 4!







Step 3





Step 4




Step 5



Step 6



Maximum Load Capacity: 45kg



**Your LINEAR WORKSTATION (2CTNS)
is now complete and ready for use.**