

Product Safety Recall

Product Information

Product Part Number and Description

GT412 GarageTuff **1200kg Trolley Jack**

Batch #: 3264-08.2012

Defect:

The jack does not meet the requirements of AS/NZS 2615:2005

- Clause 5.5 whereby the overload protection maybe greater than the 15% and
- Clause 6.6 Overload test
- Clause 6.7Y Eccentric load test bent radius link.

Effected Products:

GT412 Hydraulic jack batch no 3264-09.2012 supplied from November 2012

The batch/serial number is located on the top of the jacks black cover plate.

What Should Consumers do;

Consumer Actions:

Stop using your jack immediately and return to the place of purchase, for an exchange or full refund.

Further Information:

Supplier Information:

Automotive Brands Group Pty Ltd
76-92 Station Street
Nunawading, VIC, 3131
Ph: (03) 8878 1111



See www.recalls.gov.au for
Australian Product Recall Information